Date:

Thursday, 5/3/2007 11:39:27 AM

User:

Kim Johnston

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Type

Job Number

: 32207

Estimate Number

: 12522

P.O. Number

:NIA : 5/3/2007

This Issue Prsht Rev.

: NC

: NA

: 31171

Previous Run Written By

Checked & Approved By

Comment

First Issue

New Issue 06-09.06 EC : Est Rev:A

: SMALL /MED FAB

S.O. No. : NA

Drawing Name

Part Number

Drawing Number

: D35311

Project Number

: N/A

Drawing Revision

Material

Due Date

· UNDER REVIEW

: BRACKET ASS'Y

5/28/2007

70,70,70

3 Um:

Each

Additional Product

Job Number:

Seq. #:

Machine Or Operation:

Description:

1.0

M6061T6S040

6061-T6 .040 Sheet

07/05/09

Comment: Qty.:

0.3972 sf(s)/Unit

Total:

1.1916 sf(s)

6061-T6 .040 Sheet (M6061T6SQ40)

FLOW WATER JET



2.0

WATER JET

Comment: FLOW WATER JET

1-Cut as per Dwg D3531

Dwg Rev: Prol Prog Rev: pre

SAD 07/05/09

2-Deburr if necessary

3.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE





Comment: INSPECT PARTS AS THEY COME OFF MACHINE

SECOND CHECK

05/09

4.0

QC8



Comment: SECOND CHECK

BRAKE NO

NC BRAKE

56

3

5.0

Comment: NC BRAKE

Bend as per Dwg D3531



07/05/183

Dart Aerospace Ltd

W/O:			WORK ORDER CHANGES										
DATE STEP		PROCEDURE CHANGE					Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		8	4										
						24-							

Part No:	PAR #:	_ Fault Category:	NCR: Yes No DQA: £	Date: <u>07/45/24</u>
			QA: N/C Closed: _	Date:

NCR:	•	WORK ORDER NON-CONFORMANCE (NCR)									
DATE STEP		Description of NC		Corrective Action Section B	Verification	Approval	Approval				
DAIL	SILF	Section A	Initial Action Description Chief Eng Chief Eng		Sign & Date	Section C	Chief Eng	QC Inspector			
07/05/09	z.0	A part were Scrap because of the offset (One part)		Scrap and destray and	SAO			RA			
i p		(One part)	ESIVIT		07/05/09	07/05/09	651042	2/2/04			
07/05/69	7.0	Dimension were wrong on Program (one point)		Scrap and destroy and replace	5/4) 07/ec/			M			
			asions		13/05	07/05/09	Pos1042	02/02/0			
		,				-					
		•									

NOTE: Date & initial all entries

	Thursday, 5/3/2007 11:39:28 AM Kim Johnston	Process Sheet	
. Custon	ner: CU-DAR001 Dart Helicopters	Services Drawing Name: B	BRACKET ASS'Y
Job Numi	per: 32207	Part Number: [[]	D35311
Job Number:			1
Seq. #:	Machine Or Operation:		cription :
6.0	QC5	INSPECT WORK TO CURRENT	STEP
7.0	nment: INSPECT WORK TO CL HAND FINISHING1	RRENT STEP HAND FINISHING RESOURCE	#1
7.0	HAND-FINISHING I	HAND FINISHING RESOURCE	
Cor	nment: HAND FINISHING RESO Chemical Conversion Co	E . / /	Bl 07/05/23 (3)
8.0	QC3	INSPECT POWDER COAT/CHE	MICAL CONVERSION
Cor	nment: INSPECT POWDER CO	AT/CHEMICAL CONVERSION	C7/5/24 (3)
9.0	PACKAGING 1	PACKAGING RESOURCE #1 ENGINEERING APPROVAL	5.24
Cor	nment: PACKAGING RESOURO		
	Location:		(3)
10.0	QC21	FINAL INSPECTION/W/O RELEA	3
Cor	nment: FINAL INSPECTION/W/) RELEASE	767/05/04
Job Completion			1 Stus 24
			·
			0 1
			∯ ∆les
10.0 Cor	Identify and Stock Location:	FINAL INSPECTION M/O RELEA	3)

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE	STEP	ý	PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector		
				¥	-,						
					•	· 4					
	·		- · ·		- Prop.		,				


Part No: _	· · · · · · · · · · · · · · · · · · ·	PAR #:	Fault Category:	 NCR: Yes No	DQA:	Date: _	
	<i></i>			QA: N/C	Closed:	Date: _	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Approval	Annewal			
DATE	STEP	Section A	Initial Action Description Chief Eng Chief Eng		Sign & Date	Section C	Chief Eng	Approval QC Inspector			
		•									
<u>.</u>						1.5					
			, o								
				. (2)							
		i.									

NOTE: Date & initial all entries

MANATY 1801

DESIGN B	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CA	
CHECKED PH	APPROVED	DRAWING NO.	REV. A SHEET 2 OF 3
DATE 07	.01.10	BRACKET ASSEMBLY	SCALE 1:2



D3531-1F FLAT PATTERN

D3531-P時代ACKET RETURN TO

NOTES:

1) MATERIAL: ALUMINUM 6061-T6/T62 SHEET, 0.040 THICK PER QQ-A-250/11 OR

AMS 4025 OR AMS 4027 (REF DART SPEC M6061T6S.040)

2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1

SUBJECT TO AMENDMENT

3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED 4) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED

5) BREAK ALL SHARP CORNERS TO 0.010 MAX 6) PART IS SYMMETRIC ABOUT ©

WITHOUT NOTICE

NO.

COPYRIGHT © 2007 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

DART AEROSPACE LTD	Work Order:	32207
Description: BRACKET ASSUVE	Part Number:	D35310-
inspection Dwg: D35311 Rev: PREL		Page 1 of 1

		F	irst Art	icle [rototy	pe	
	pection Sheet ing Dimension	Tolerance	Actua Dimens	Acc	ept	Reject	Method of Inspection	Comments
Ai	12.50	4/-0.030	12.40	'n	/		Very heigh	Isauce
B	0.600	+1.0.030	0.598	N N			Vern	
C	3.97	46-0.030	3.98	,			height gauge	
D	4,64	41-0.030	4.63		/		neight sauge	
E	7.09	= (0,070	5,00	09			Vern	
F	6.80	t/ 0,030	5,81		c		height sauge	
G	1.40	+60,030	1.42				height gauge	
1-1	1.62	41-0,030	1,64		1		height gage	
1,	0.38	+ 1.0.030	0.38				Vern	
J	0,19	4/10.030	1		/		height gause	and the second s
К	0.33	4-0,030	0.33				Vern	
i_	20.129	+0.005/-0.001	Ø0.1	32 4			Very	
NA.	00.196	+0.005	\$0.19	6			Vern	
И	0.040	+60.010	0.03		1		Vern	
0	2,840	1/0010	2.84	5 L			Vern	
b	. 54 . 4							
Q								
R.								
S							-	and the second s
·!			<u> </u>					
()								
V								<u> </u>
VV								
X								
Ÿ			<u> </u>					
Mea	sured by: 5	A/2 Aug	lited by:	K .	4.	Prof	otype Approva	1: MAY
	Date: 07/	05/08	Date:	07-05-09			Date	: NA 07.05
Rev	Date Cha	ange v Issue					Revise KJ/RF	ed by Approved

